

The class is subject to the port and starboard boiler main feed check valve lids and nuts being examined by the end of 4,57, also main circulating pump casing being renewed by the end of 4,57.

4E
26 JUN 1957

Engineer Surveyor Received from Chief Engineer Surveyor
"IOANNIS INGLESSIS" REPORT Gen. No. 22350

ES due 8,55, partly held 1,56, now completed.

Damage due heavy weather and some repairs carried out.

SRL.

The above items now dealt with.

The ballast pump water end; auxiliary condenser and windlass cylinder block found defective, but considered efficient meantime, and the Surveyor recommends these items be renewed by the end of 9,57.

Alterations.

Two new oil fuel settling tanks installed in accordance with the Rules and approved plans, also a new fire pump fitted.

IT IS SUBMITTED that this vessel is eligible for the record ES 1,56, subject as now recommended, without other special condition.



adlu

25.6.57



© 2021

Lloyd's Register
Foundation

008648-008655-0040

the machinery of this vessel, as far as now seen, is eligible in my opinion