

Periodical Surveys, when held, should be reported in detail and serially in the Rules and items remaining to complete the Surveys should be summarised. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to

ssAnt. No.1-3

NAME "STÖBRIS" ex "CAROLIA" Report Stockholm No. 69⁶10

THICKNESSES OF PLATING ascertained by drilling, and comparison of same with the original thicknesses.

The thicknesses are in _____ of an inch.

26 JUL 1948

PLATE.	AMIDSHIP.						FORWARD.				AFT.				REMARKS.				
	Original Thick-ness.		Thickness by drilling.		Diminution if any.		Original Thick-ness.		Thickness by drilling.		Diminution if any.		Original Thick-ness.			Thickness by drilling.		Diminution if any.	
	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.	Port.	Std.		Port.	Std.	Port.	Std.
DECK STRAKE.	H 50 ^a	40	55	10	-	I 30 ^a	40	31	-	-	40	35	40	5	-	P.O.D. Sheer.			
						H 30 ^a	35	31	-	-						The drilling amidships in the coal bunkers forward in frame space aft collision bulkhead and aft in frame space of the A.P.T. bulkhead.			
WAKE	G 55 ^a	55	43	-	12	45 ^a	40	40	5	5	45 ^a	48	48	-	-				
low	F 45 ^a	48	48	-	-	40 ^a	48	40	-	-	40 ^a	40	-	40	-				
	E 50 ^a	55	51	-	-	40 ^a	48	48	-	-	40 ^a	40	40	-	-				
	D 50 ^a	57	40	-	10	40 ^a	43	51	-	-	40 ^a	40	40	-	-				
	C 55 ^a	48	48	7	7	50 ^a	40	40	10	10	40 ^a	51	51	-	-				
	B 45 ^a	43	43	2	2	45 ^a	43	43	2	2	40 ^a	57	48	-	-				
	A 50 ^a	57	57	-	-	45 ^a	57	57	-	-	45 ^a	67	67	-	-				
KEEL	70 ^a	59	-	11	-	55 ^a	67	-	-	-	55 ^a	71	-	-	-	Thoma Weber.			

Drillings at ends to be made in the vicinity of the peak bulkheads.

Thoma Weber.

© 2021

Lloyd's Register Foundation

008648-008655-0082

ms & Fastenings _____ Cement or Aspnalt _____ Rudder _____ Oil Bunkers _____ Scuppers _____