

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME Stl. S.S. LA PLAYAReport Div.No. 86378**For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.**

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Nature of Survey \_\_\_\_\_ When due \_\_\_\_\_

✱ 100 A.I. (Steel)  
With freeboard  
1.24 Bkn.

4 Dks. (Stl. weather w.s.)

Cell D.B. 272' 48" t, FPT 52 t, APT 13 t

+BK 1/2  
FK, 6m, Lloyds A+CP, P35', B104', F41',

4 BH, Intermediate bulkhead in fore hold dispensed with

Date of build 11.23



© 2021

Lloyd's Register  
Foundation

29.1.24

008656-008668-0049