



Lloyd's Register of Shipping,

95, Bothwell Street, GLASGOW, C.2.

Reports encl.

15th April, 1948.

Dear Sir,

In answer to the London letter of the 13th instant regarding the testing of the tanks of the Steamer "OILFIELD", I have to maintain that only the side tanks were tested to survey requirements.

The main tanks were known to be leaking at some of the hard spots etc., and would not have given satisfactory tests.

I agree with the state of tank testing given in Mr. Dixon's letter dated 10.4.48.

The reports forwarded are returned herewith.

I am, Dear Sir,
Yours faithfully,

The Secretary,
GLASGOW.



© 2021

Malcolm
Lloyd's Register
Foundation

008658-008668-0127