

ACTION is DEFERRED for examination
in drydock after grounding.

of Surveyors.....

Received from Chief Surveyors.....

NAME "GEO G" REPORT Bos. No. 4800.

For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR.~~

Cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.).

Equipment. When due.....

NOTED

SUBJECT to 30 fathoms of chain cable
being supplied at the earliest opportunity.

ACTION is DEFERRED for examination
in drydock after grounding.

IN S.R.L.
Drydocking (grounding).

OFFICE NOTE:
Structural stiffening fitted - Bal. 10,52.
Locking brackets fitted - Bal. 9,53.

AMM.
16-1-58

C.S.S. Records Dept.
to note.



© 2021

Lloyd's Register
Foundation

008609-008618-0208