

# REPORT of SURVEY for REPAIRS, &c.

Date of writing Report... 19... When handed in at Local Office... 19... Port of London

No. in Reg. Book. 5940 Survey held at on the Wood, Iron or Steel, S.S. Princess Juliana Date, First Survey... Last Survey... 19... (No. of Visits)

TONNAGE:-  
GROSS 266  
UNDER DK. 236  
NET 104  
Built at Hull By whom Charles C. St. When 1905 MONTH Feb.  
Owners Hampshire Birell & Co. Ltd. Owners' Address...  
Managers... Port belonging to Fleetwood

Surveyed Afloat or in Dry Dock? Name of Dock... Destined Voyage...  
WB=CelDBorDBa feet; uE&B feet; f feet }  
total capacity tons. FPT tons; APT tons; MT feet tons. }

N.B.—All alterations in the existing records should be underlined.  
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 84675 Port Liv.

CHARACTER. X for Special Survey. Date of last Survey and of Periodical Survey.	Years expired or about to expire.	Machinery and Boiler Surveys (including date of N.B., if any).
<u>+100 A1.</u>		<u>Jul 9.19.</u>
<u>Steam Tractor.</u>		<u>1.23.</u>
<u>1.23.</u>		<u>T.S. 1.23 C.L.</u>
<u>S.S. Fet. No. 3 - 9.19.</u>		

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined  
Society's Freeboard (if assigned) as painted on Ship and now verified } ft. ins.  
Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

DAMAGE REPAIRS :-	Shell Plates.	Frames.	R. Frames.	Floors.	Beams.	Str. Plates.	Dk. Plates.	Other Items :-
and Fair'd or Repaired								
Repaired in place								

CONDITION OF THE	State if Tanks have been examined inside	Dblng. Plates under Sounding Pipes	Copper, or Y.M. of Wood Vessels
State if Tanks now tested	Engine Room Skylights	(State if on Felt.)	When put on, Month Year
Bulkheads	Coal Bunkers, Open'gs, Lids, &c.	Boats	
Ceiling	Scuppers	Masts, Yards, &c.	
Cement or Asphalt (State white.)	Cargo Hatchways	Condition, how ascertained	(State if wedges removed)
Rudder	Hatches	Sails	
Steering gear and its connections	Planking of Wood Vessels	Equipment letter	
Windlass	Caulking ditto	Anchors, No. of	
Have Pumps now been examined and found efficient?	Treenails ditto	Cables (State if now ranged)	
Have Sluice Valves now been examined and found efficient?	Breasthooks & Stemson ditto	length size	(on board)
Have Watertight Doors now been examined and found efficient?	Transoms, Pointers, & Crutches ditto	Rule length size	
Have Ventilators and their Coamings been examined and found efficient?	Timbers of Frame at openings ditto	Hawser & Warps	
	Ditto ditto at other places ditto	Standing & Running Rigging	
	Stringers, Clamps & Shelves ditto		
	Salting ditto (State if examined.)		

Observations, Opinion as to Class, Recommendation, &c.:-  
Clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this, for example:— "to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of Survey," "to remain as classed and to have record of survey, 1,24, and the notations of ss No. 1-24 and ptND15, &c."

	£	:	:	Fees applied for,
Repair Fee (if any)				19
Chargeable				19
(if any)				

Surveyor to Lloyd's Register of Shipping.



Lloyd's Register Foundation

Is Certificate required? If so, to be sent to