

179

Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 20th. February 1930.

Cert. No. 2405.

This is to Certify that at the request
of Messrs. The Kobe Steel Works Ltd., Kobe,
the Open Hearth Steel Forgings ~~in Castings~~ named below ~~were~~ examined and
tested at their works on 12th. and 15th. February 1930 (2 visits)
and found to be as far as could be ascertained, sound and free from defect.
Two (2) Intermediate shafts 15½" dia. (black)
Examined in black forged condition.

~~Drop tests~~

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x 1" x 180°
179 D 3533A1	31.3	32	Good.
179 D 3523A1	32	33	"

These shafts are intended for Yokohama Dockyard

Ship No. 179 or 180 and ~~was~~ have been stamped as follows:-

Fee Yen 60.00

Expenses ,, 1.00

TEST MARKS AS ABOVE

LLOYDS

No. 2405


15-2-30

H.B.G. L.R.

R. Watt

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."



Lloyd's Register of Shipping

(MEIKAI BUILDING)

32.32, AKASHI-MACHI,

KOBE, 8000, February 1930.

Cert. No. 2405.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe,

the Open Hearth Steel Forgings or Castings named below were examined and tested at their works on 12th and 18th February 1930 (2 visits)

and found to be as far as could be ascertained, sound and free from defect.

Two (2) Intermediate shafts 15" dia. (black)

Examined in black forged condition.

Test Mark	Tensile in Tons	Elongation % in 8"	Bend 1" x 1/4" x 180°
D 3858A1	51.3	23	Good.
D 3853A1	50.35	23	"
D 3878A1			
D 3878B1			


These shafts are intended for Yokohama Dockyard and have been stamped as follows: -

TEST MARKS AS ABOVE
LLOYDS
No. 2405
15-2-30
H.B.G. L.R.

Fee 100 Yen
Expenses 1.00

Surrogate to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default or negligence of the Surveyors, other Officers or Agents of the Society."



Lloyd's Register
Foundation