

# Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 14th. March 1930.

Cert. No. 2402.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe.

the Open Hearth Steel Forgings ~~and Castings~~ named below <sup>was</sup> ~~have~~ examined and tested at their works on 7th. and 8th. February 1930.

and found to be as far as could be ascertained, sound and free from defect.

One (1) Intermediate Shaft 15" black forged diam.

Examined in black forged condition.

Drop tests:

Test Mark	Tenacity Tons/sq in	Elongation % in 2"	Bend 1" x 1/4" x 180°
179 D 3515B1	32.2	55	Good.

This Shaft is

intended for Yokohama Dockyard

Ship No. 179 or 180

and <sup>has</sup> ~~have~~ been stamped as follows:-

Fee Yen 30.00


Expenses ,, .50

D3515B1.  
LLOYDS  
No. 2402.  
8-2-30  
A.W. L.R.

*Qulatt*

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."





# Lloyd's Register of Shipping

(MEIKAI BUILDING)

35, AKASHI-MACHI, CHUO-KU, KOBÉ

14th March 1930

Cert. No. 8402

This is to Verify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe,

the Open Hearth Steel Forgings were examined and

tested at their works on 7th and 8th February 1930.

and found to be as far as could be ascertained, sound and free from defect.

One (1) Intermediate shaft 15" dia forged steel.

Examined in black forged condition.

Drop tests:

Test Mark	Tensile in Tons	Elongation % in 8"	Bend 1" x 1/2" x 180°
D 351581	35.2	35	Good

This shaft is intended for Yokohama Dockyard


and has been stamped as follows:—

RESISTANCE  
LLOYD'S  
No. 8402  
8-2-30  
A.W.L.R. L.R.

Fee 30.00  
Insurers' 50.00

Surveyor in Lloyd's Register

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy of report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society.



Lloyd's Register  
Foundation