

Lloyd's Register of Shipping,

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 20th. February 1930.

Cert. No. 2393.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe.

the Open Hearth Steel Forgings ~~on Castings~~ named below ~~were~~ ^{was} examined and tested at their works on 3rd. and 4th. February 1930.

and found to be as far as could be ascertained, sound and free from defect.

One (1) Intermediate Shaft 16" dia. (black)

Examined in black forged condition.

Drop tests:

| Test Mark | Tenacity Tons/sq in | Elongation % in 2" | Bend 1" x 1/2" x 180° |
|-----------|------------------------|-----------------------|--------------------------|
| D 3515A1 | 32.7 | 32 | Good. |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |
| | | | |

This shaft is intended for Yokohama Dockyard

Ship Nos. 179 or 180

and ~~has~~ ^{have} been stamped as follows:-

Fee Yen 30.00


Expenses "

D3515A1
LLOYDS
No. 2393
4-2-30
H.A.G. L.R.

Adlatt

Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
"While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society or for any error of judgment, default, or negligence of the Surveyors, other Officers or Agents of the Society."



Lloyd's Register
Foundation

008679-008690-0330

Lloyd's Register of Shipping

(MEIKAI BUILDING)

32, AKASHI-MACHI,

KOBE, 20th February 1930.

Cert. No. 2393.

This is to Certify that at the request

of Messrs. The Kobe Steel Works Ltd., Kobe.

the Open Heart Steel Forgings on ~~drawings~~ named below ~~was~~ examined and tested at their works on 3rd and 4th February 1930.

and found to be as far as could be ascertained, sound and free from defect.

One (1) Intermediate shaft 18" dia. (black)

Examined in black forged condition.

Proprietors:

| Test Mark | Tensile in Tons/sq in | Elongation % in 8" | Bend 1" x 1/4" x 180° |
|-----------|-----------------------|--------------------|-----------------------|
| D 2512A1 | 22.7 | 22 | Good. |
| | | | |
| | | | |
| | | | |
| | | | |

intended for Yokohama Dockyard


and has been stamped as follows:-

D 2512A1
LLOYDS
No. 2393
4-2-30
H.A.G. L.R.

Yen 80.00

Surveyor to Lloyd's Register.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—
While the Committee use their best endeavours to ensure that the functions of the Society are properly executed, it is to be understood that neither the Committee nor the Society are under any circumstances whatever to be held responsible for any inaccuracy or error in the report or certificate issued by the Society or its Surveyors, or in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or negligence of the Surveyors, other Officers or Agents of the Society.



Lloyd's Register
Foundation