



# Lloyd's Register of Shipping.

Merchants' Exchange, Bute Street,  
Cardiff, *25 June 1921.*

Reference

S. The Secretary, London.

Sir,

In reply to clearing letter of yesterday, with reference to Q. No. 42713 on steamer "MANOA", I beg to state that the pitting of outside plating extended over 4 strakes, from below turn of bilge to about light water-line, right fore and aft, but chiefly amidships and aft. Also, the starboard side was more seriously affected than port side.


63 plates were sufficiently affected to require repair, and about 1000 pit-holes were repaired by the Electric welding process, as reported.

I am, Sir,

Yours obedient servant

*Reece*

008691-008699-0238





Referred to the Chief Ship Surgeon.

*[Handwritten signature]*

Also for Mr. J. W. Hill to note.



© 2021

Lloyd's Register  
Foundation