

2500.12.19.

1

Sent to Chief Surveyors

Received from Chief Surveyors

VESSEL'S NAME Wood Motor Ship 'PARTHIA'

Report

Pld.

No. 577
603

For the CHIEF SHIP SURVEYOR

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24.5.92.)

Nature of Survey

When due

Extensive repairs have been effected to fire damage.

30 fathoms of chain cable require to be supplied to bring equipment up to the requirements of table 31.

12 A.1. Salted & Specially treated
1 Dk. Well Dk.
A & C.P. 264', B 32', F 36'

Subject to 30 fathoms of chain cable being supplied, also subject to a special survey equal to a half time survey at four & eight years.

It is concluded drip trays have been fitted & other means adopted to prevent the leakage of oil into the bilges & saturation of woodwork but the Surveyors should be requested to state if this is

15/11/20

Lloyd's Register
Foundation