

Chief Ship Surveyor

Received from Chief Ship Surveyor

18 MAR 1926

AME Wood Sec. "RUTH".

Rpt. Cpn.

No. 7207

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/02.)

Survey

The class is subject to a special survey equal to a half time survey at 8 years from date of build.

The Copenhagen Surveyors report the vessel examined in dry dock after contact with ice, beaching and subsequent sinking.

The Surveyors recommend repairs to stem, keel, keelsons, outside planking and chafing plates, caulking of outside planking and decks, that a number of extra bolts be fitted in the outside planking, the motors be lifted for the examination of the keelsons, minor repairs and some cleaning and further examination before the vessel proceeds to sea.

It is submitted action be deferred and the Owners informed of the Surveyors' recommendation. *asked to arrange*

for the necessary repairs to be effected before the vessel proceeds to sea.

[Handwritten signature]

© 2021

Wanna
18.3.26.

Lloyd's Register
Foundation

008700-008710-0060