

DISCLOSED

SECTION No. ~~206~~

10 MAY 1928

205

urveyors

Received from Chief Surveyors

NAME s.s. "PIONEER"

Report

London

No. 92621a.

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)



urvey

When due

The screwshaft survey became due 3.28.

In reply to the usual notice the Owners state that, as in the case of their other pilot steamers, they propose to allow the class to lapse.

IT IS SUBMITTED the vessel's class be omitted from the reprint of the Register Book.



10.5.28.



© 2021

Lloyd's Register
Foundation

008700-008710-0216