

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME Steel S.S. "EMBLETON"

Rpt.

Hul.

No. 32114.

marks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Survey

Classification.

To complete the Survey a 1st & 2nd Bower Anchor of proper weight & test 60 fathoms of chain cable require to be supplied.

The Newcastle Surveyors should be advised & requested to forward a report on form 8 when the Survey has been completed.

Ln 519.



2021
15-9-20

Lloyd's Register
Foundation

008700-008710-0260