

1

Sent to Chief Surveyors.....

GB

Received from Chief Surveyors.....

VESSEL'S NAME 'WINSTON CHURCHILL' REPORT Sld. No. 35240For the CHIEF SHIP SURVEYOR and ~~CHIEF ENGINEER SURVEYOR~~

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey..... ~~When due~~

The class is subject to hatch covers being fitted to 2nd deck at No.6. hatchway at the first opportunity, and to (a bower anchor and 45 fathoms of chain cable being supplied).

The Owners Superintendent visited the Office to-day as arranged and discussed the question of the necessity for hatch covers to 2nd deck at No.6. hatchway as above.

The accommodation casing sides are to be maintained forming a trunked hatch.

IT IS ACCORDINGLY SUBMITTED the condition of class pertaining to hatch covers may now be deleted.

IT IS FURTHER SUBMITTED the vessel's class be continued subject to (a bower anchor and 45 fathoms of chain cable being supplied), but without other condition.

As Now. (Subject).
Without



© 2020

Lloyd's Register
Foundation

008751-008752-0035