

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

2nd March, 1962.

Dear Sir,

Trawler "BRACONGLEN".

C.
RNC.

With reference to the classification in this Society's Register Book of the above named trawler, the Society's Surveyor at Colombo has reported that the Special Survey which became due in January, 1961, has been held, except for some repairs which are required to port and starboard "A" strake plates between frames 22. and 23 from aft, and the renewal of 60 fathoms of chain cable.


This chain cable was reported last August to be seriously worn, to a mean diameter of 5/8", and it was recommended that it be no longer used.

The Committee naturally attach considerable importance to the efficiency of anchors and cables, on board a vessel classed with this Society, and must regard the renewal of these 60 fathoms as part of the Special Survey for which the year of grace has now expired. They have, therefore, instructed me that this survey must be completed in all respects before the end of May next if further maintenance of class is desired.

I shall, therefore, be obliged if you will kindly let me know as soon as possible what arrangements you propose to make to fulfill this requirement.

Yours faithfully,

c.c.CBO.



© 2021

Clerk to the
Classification Committee.

Lloyd's Register
Foundation

008753 - 008758 - 0076