

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic Address { Inland: Committee, London, Telex
 { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

Enclosures.

2nd March, 1962.

Dear Sir ,

Trawler "BRACONGLEN".

C.

RNC.

Your report No. 5063 has received the consideration of the Committee today, and I enclose for transmission to the appropriate Government Department a letter which I have today been requested to address to them concerning the completion of the overdue survey.

According to your letter of the 19th December last, the Owners stated that the defective shell plating between frames 22 and 23 had been doubled. This point, of course, requires verification and until a satisfactory report has been received, this work must be regarded as still outstanding.

Yours faithfully,

c.c. C.L.F.

Clerk to the
Classification Committee.

B.E.J. Borkett, Esq.,
COLOMBO.



© 2021

Lloyd's Register
Foundation

008753 - 008758 - 0077