

24 JUN 1949

"ZAHRA"

L.A. 12635.


IT IS SUBMITTED that before this case receives consideration the Lloyd's Agents' Surveyors at Casablanca should be requested to state whether his survey of the vessel's machinery included the ship's side sea connections, the thrust and intermediate shafts with bearings, the examination under working conditions of the oil fuel and the fire extinguishing installations and the adjustment of the safety valves of the boilers to their working pressure of 180 lb. per sq. inch.

He should also be requested to state the date, or at least the month when the screw shaft was examined in order that the correct record of Screw Shaft Survey may be assigned.

Note: Provided the above requirements have been complied with the vessel is eligible for the Records LMC 12.48,  
S with date.

B.P.2.

23. 5. 49.



© 2021

Lloyd's Register  
Foundation

008753-008758-0164