

COPY

LLOYD'S REGISTER OF SHIPPING

71, Fenchurch Street, London, E.C.3

Telegraphic { Inland: Committee, London, Telex
Address { Overseas: Committee, London, E.C.3

Telephone: ROYal 9166
Telex No.: 24305

18th March, 1963

C
MWK/MRN
Dear Sirs,

CLASSING LETTER

14076 "HEIGA SMITH". As recommended.

According to the First Entry Report the Donkey Boiler longitudinal seams are lap riveted, and I shall be glad if you will ascertain from the Owners what arrangements can be made to have the requirements of Instructions to Surveyors, Part 3b, 1957, Amendment No.5 complied with.

Following a Survey carried out at Copenhagen on the 8th February, it was recommended that the propeller be specially examined and dealt with at the next Drydocking before the end of May 1963, and I shall be glad if you will inform the Owners accordingly.

14084 "LOKE". As recommended. With reference to the entry against Certificate No. 103, in your Report 8 (Eq), it is concluded that the weight of 1607 K.G. is in error.

14109 "ORINOCO" R.M.C. As recommended. I have to inform you that the items listed under Items 11, 12, 15 and 16 as being outstanding were examined in July or September 1962, and do not require to be examined for completion of the present Survey.

Yours faithfully,

pro Clerk to the
Classification Committee

The Surveyors,
STOCKHOLM.

008753 - 008758 - 0197

© 2021

Lloyd's Register
Foundation