

EA

COPY

Ship's name "HELGA SMITH"

Port GOT

No. 28453

Last survey date 20.3.63

Class is subject to

NONE

S.R.L. Appendix (as before ~~or~~ none)

Nature of present survey (afloat and in drydock)

Temporary repairs to damage
caused by heavy weather.

Recommendation

SUBJECT to fractures in sheerstrake, deck in way
of deckhouse front (p & s), in sheerstrake in way
of freeing ports forward of midship deckhouse and
in sheerstrake in way of aft end of recess for
gangway (s.s) being specially examined and dealt
with as necessary by 5.63.

As Now Subject.

IN S.R.L. APPENDIX

(Bottom plating stiffened with minor corrugations unfaired).

(Shelter deck plating to be kept under observation - Wavy)

OFFICE NOTE.

Bottom plating stiffened - Ans. 9.53,
with minor corrugations unfaired.

C.S.S. Records Dept.
to note.



Lloyd's Register
Foundation