

| | |
|--------------------|----------------|
| " <u>SURINAM</u> " | LMC due 3,54 |
| | T.S. " 1,57 |
| | |
| " <u>TAMARE</u> " | LMC " 8,53 |
| | T.S. " 10,55 |
| | |
| " <u>ULE</u> " | LMC " 11,53 |
| | T.S. " P 11,54 |
| | S 2,55 |

In reply to the Vancouver Surveyors' letter of 14.10.54. they should be informed that, with the vessels being towed and not using their engines or boilers, no special requirements are necessary.

It the Owners desire to retain Classification the Special Survey of machinery should be carried out on each vessel, also steam pipes.

The port main engine crankshaft after journal of the "SURINAM" was recommended to be renewed by 5,54.

adli

26.10.54.



© 2021

Lloyd's Register
Foundation

008739-008764-0021