

COPY

LLOYD'S REGISTER OF SHIPPING

UNITED WITH THE BRITISH CORPORATION REGISTER



Port Aruba, N.W.I.

4th February, 1954

This is to Certify that I have

Surveyed the Boiler and Machinery of the TSS. "SURINAM"

3156 tons gross of Maracaibo, on January 30, 1954 and subsequent dates, on account of repairs to Port Engine crankshaft and thrust bearing.

and that I have transmitted to the Committee of Lloyd's

Register of Shipping, London, a Report stating that all

recommendations made by me in connection therewith have

been carried out to my satisfaction, and that I have

Recommended that the record of PLMC **be retained, subject to**

Port Engine crankshaft aftermost journal being renewed within three months.

be made in the Register Book in the case of this vessel.

W.D. Wardle

Engineer Surveyor to Lloyd's Register.

This Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—

While the Committees of the Society use their best endeavours to ensure that the functions of the Society are properly executed, it is understood that neither the Society nor any Member of any of its Committees is under any circumstances whatever to be responsible for any inaccuracy in any report or certificate issued by the Society or its Surveyors, or in any entry in the Register or other publication of the Society, or for any error of judgment, default or negligence of any of its Committees or any Member or the Surveyors, or other Officers or Agents of the Society."

