

Hull. Cont.

24th September, 1952.

E KANIN" 58587. As recommended.

58591 "KINGSTON AGATE". As recommended, except that a fresh record of Docking Survey 8,52 has been assigned.

58607 "SANDHOE". As recommended, except that a record of BS 7,52 has been assigned.

"GULL". Before your report No. 58630 receives the consideration of the Committee it is concluded the Owners have been advised that as the cementing of the bottom has been dispensed with an annual examination will be required.

In connection with the chain cable, I shall be glad if you will furnish particulars of where and when they were tested and the name of the Superintendent, as this information appears to have been omitted from your report.

I would inform you that information regarding the screwshaft liners, bilge pump suction and fire extinguishing apparatus has been omitted from your report. At the same time a builder's signature is required for this part of the survey and in view of this I enclose herewith the report for completion.



© 2021

Lloyd's Register
Foundation

008759-002764-0182