

Hul. 58630.

"GULL"

The Hull Surveyors have omitted from their report the necessary information regarding the screw shaft liners, bilge pump suction, and fire extinguishing apparatus. Also they have not obtained a builder's signature for this part of the Survey.

IT IS SUBMITTED that before the case receives consideration, the report should be returned to the Hull Surveyors for completion.

L. B.
23. 9. 52.

For H. L. L. Hull 24/9
L. B.

once after Cl. L. L. please.



© 2021

Lloyd's Register
Foundation

009759-008764-0183