

Class is subject to the port cable lifter gearwheel of windlass being specially examined by 9.56.

4E

Inspected by Chief Engineer Surveyor.....

Received from Chief Engineer Surveyor.....

12 APR 1957

VESSEL NAME "GUMHURYAT MISR"

REPORT ALX.

No. 4864.

Wear and Tear Repairs - Main circulating pump crankshaft renewed.

SRL This item specially examined and continues efficient. Surveyor recommends it to be deleted from SRL.

IT IS SUBMITTED that this vessel is eligible to remain as classed without special conditions.

Endorsement "B" - Port cable lifter gearwheel of windlass repaired.

<sup>End</sup>  
11.4.57.



© 2021

Lloyd's Register  
Foundation

008759-008764-0207