

2

5th January, 1962.

two

KOBE.


9756, 96 - As recommended.

"IYEHARU MARU" 9680 - As recommended. According to the records here two auxiliary engines are fitted on the port side as follows:-

Port Outboard 100 KW
Port Inboard 260 KW

You should identify the auxiliary engine examined at this time. It would also appear that two fuel transfer pumps are fitted, and the pump other than the port pump examined at this time requires to be examined. You should therefore request the Owners to make arrangements for this matter to be dealt with at an early date.

© 2020



Lloyd's Register
Foundation

5110-266800-596800