

3 - JAN 1962

Received from Chief Ship Surveyor.....

SHIP'S NAME "HIYEHARU MARU" REPORT Kob. No. 9680

Outstanding Conditions of Class: SUBJECT to the sternframe at lower end of propeller post (E.W.8,59 and previously) being specially examined at the next drydocking.

R.L. Appendix. (As before ~~or None~~)

Surveys due: A SPECIAL SURVEY (B) became due 9,61.

Nature of Present Survey: (Afloat and in dry dock)

Docking: SPECIAL SURVEY (B): Wear and tear repairs: Examination of the conditions of class.

Special Features:

Interim Certificate in order (Yes-~~No~~-None)

Items Outstanding: (If any for S.S.)

NONE.

~~to be~~ completed ~~by~~

Recommendation:

SUBMITTED record of 'DS 10,61' and Notation of 'SS 11,61' be assigned as recommended, but without special conditions.

DS 10,61
SS 11,61 Without.

IN S.R.L. APPENDIX.

Bottom shell plates A.7,8,& 9 (p.s. from aft) slightly corrugated.



© W.S. 1
13.12.61.

Lloyd's Register
Foundation

008765-008772-0126
2710-266800-596800