

This vessel has the notation of  
CLASS SUSPENDED MANY SURVEY INCOMPLETE

4E

Chief Engineer Surveyor

Received from Chief Engineer Surveyor

NAME JSLAS MARVINAS

REPORT

MVO

No. 1035

Loc due 7.54 partly held as CL now advanced  
LBS. " 7.54 " " 11/55 " "

Working Screw shafts drawn and examined  
Port screw shaft found badly pitted, spare <sup>new</sup> screw shaft fitted

It is submitted no action necessary.

Port S<sup>(N)</sup> (CL) 11.56 when the class has been  
reinstated

© 2021  
TORSIONAL  
ENDORSEMENT CASE

Lloyd's Register  
Foundation

008778-008785-0019