

COPY

Lloyd's Register of Shipping,

71, Fenchurch Street, E.C.3.

18th August, 1947.

Dear Sirs,

I am in receipt of your letter of the 28th ultimo, enclosing First Entry Reports on the Main and Donkey Boilers and the Electrical Equipment of the steamer "HEMBURY", and have to inform you that these are in order except that particulars of safety valves on the main boilers are not understood. The Rule size for safety valves for a Heating Surface of 3002 square feet is 19.24 square inches, and I shall be glad to receive your remarks on this point.

I would also point out that the pumping plan shows 3 $\frac{1}{2}$ " branch suction in the machinery space, two of these at the forward end of the boiler room and two at the after end of the engine room, also two 3 $\frac{1}{2}$ " direction suction in the engine room, and I have to request that you will confirm that all these are fitted, as reference is made only to two 3 $\frac{1}{4}$ " branch suction.

I would add that according to the particulars given the M.N. should be 437.

Yours faithfully,

Harveyors,
NTWERP.

Clerk to the
Classification Committee.

008778-008785-0267