

REPORT of SURVEY for REPAIRS, &c.

Date of writing Report 10th January 1920 When handed in at Local Office 10th January 1920 Port of Jacksonville, Fla.No. in Reg. Book. Survey held at Savannah, Ga. Date, First Survey 4 Jan. 1920 Last Survey 9th Jan 1920on the ~~Wood, Iron or Steel~~ Steel Steamer "SALACIA" Master A. B. ClarkeTONNAGE:— Built at Glasgow By whom G. Connell & Co Ltd When 1912 MONTH. 10GROSS 5261 Owners Donaldson Line Ltd (Donaldson Bros Ltd Mgrs) Port belonging to GlasgowUNDER DK. 4964 Owners' Address _____NET 3311 (if not already recorded in Appendix to Register Book).Surveyed Afloat or in Dry Dock? Afloat Name of Dock _____ Destined Voyage Savannah to Liverpool

WB=Cell DBorDBa feet; uE&B feet; f feet; f Particulars of Classification (which must be inserted precisely as in Register Book & Supplements).

total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.

If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, girders, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 79958 Port Port

(Periodical Surveys, when held, must be reported in detail and serially in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported, the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

Society's Freeboard (if assigned) as painted on Ship and now verified _____ ft. _____ ins.

In damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined? _____

Was a damage report made by anyone else? If so, by whom? _____

REPAIRS, OR EXAMINATION AS PER RULE, FOR carrying out requirements for vessels fitted for oil fuel.Ceiling was removed & relaid on 2" (two inch) wood battens laid transversely.The material & workmanship is good.