



# LLOYD'S REGISTER OF SHIPPING

Djalan Raja Darmo No. 130, Sourabaya, Indonesia

Telegrams: Surveyor, Sourabaya

Telephone: Darmo No. 120

Sourabaya, 23rd. April 1959.

RECEIVED

4 MAY 1959

25/5

M.S. "INSUMAR".

Dear Sir,

Further to my previous correspondence regarding the reclassification of the m.s. "Insumar".

The surveys have proceeded satisfactorily, so far, with the exception of the anchor cables and they, excepting three lengths, are below renewal size and the Owners are having great difficulty in obtaining new cable.

If the Owner obtains a used cable of the correct size and a proof test is carried out, by using weights on a crane, would this be acceptable as a temporary measure until new cable can be obtained.

When new cable can be obtained, the manner of its purchase may make it very difficult to obtain certificates. If this position should arise would it be in order to accept the cable, if satisfactory bend and tensile tests were taken from a link and a proof test carried out.


Another problem is a lack of a Load Line Certificate or C 11 Report on board or in the Owners possession, the gentlemen that had control of the ship during the past year removed all papers before leaving. If you would forward the procedure for putting this matter to rights I would be most obliged.

Yours faithfully,

B. Borkett.

B. BORKETT.

The Secretary,  
L O N D O N.



Lloyd's Register  
Foundation

008854 - 008811 - 0120

reference  
Assn (S).

7/5/59



THE SECRETARY,  
LLOYD'S REGISTER

H F

COPY TO  
B. BOWMAN

CLASSIFICATION

*[Handwritten signature]*

*R.A.F.*

Yours faithfully,  
*[Handwritten signature]*

matter to which I would be most obliged.  
If you would forward the brochure for buying this  
during the past year, removed all before the ship  
possession, the Gentlemen that had control of the ship  
case of C II report on board of in the Owners

Another problem is a lack of a good true Certifi-  
cate carried out.

and renewal tests were taken from a link and a brood  
be in order to accept the cable, if satisfactory, then  
certificates. If this position should arise, would it  
business may make it very difficult to obtain

When new cable can be obtained, the manner of its  
measure until new cable can be obtained.

on a cable, would this be acceptable as a temporary  
size and a brood test is carried out, paying weight

If the Owner obtains a new cable of the correct  
cable.

Owners are having great difficulty in obtaining new  
excepting three lengths, are below renewal size and the  
with the exception of the anchor cables and they,

the anchors have proceeded satisfactorily, so far,

the recertification of the m.s. "Inverness".  
Further to my previous correspondence regarding

"M.S. INVERNESS".

Dear Sir,

© 2021

Lloyd's Register  
Foundation

1991 1794. 1795, 1796, 1797, 1798, 1799.

1991 1794. 1795, 1796, 1797, 1798, 1799.

LLOYD'S REGISTER OF SHIPPING