

LLOYD'S REGISTER  
RECEIVED  
9 JUL 1929  
LONDON

Time of Receipt 10-10 A.M.

# TELEGRAM.

B<sup>S</sup>  
or  
C<sup>S</sup>  
M  
**H**

POST OFFICE



TELEGRAPHS.

No. ....

Office Stamp.

|                         |   |  |               |
|-------------------------|---|--|---------------|
| Charges to pay<br>s. d. | This form, and if possible, the envelope should accompany any enquiry respecting this Telegram. |  | Office Stamp. |
| Received from           | Office of Origin, Foreign Number, No. of Words, Date, Time handed in, and Service Instructions. |  |               |
| By                      | : 1048 CURACAO 12 4 8/7 500 PM HOLLANDRADIO   |  | Sent          |

(34615) 3750 pads 11 28 Hw E.223

COMMITTEE LONDON =

ZULIAITSUB LYGUKKYWHO =

- ZULIA
- ITSUB - What is diameter of crankshaft?
- LYGUK - Minimum
- KYWHO - Approved



© 2021

Lloyd's Register  
Foundation

008804 . 508811 - 0190

Referred to the Chief Engineer Sir

*J.H.B.*

-9 JUL 1929

It is submitted that Surveyors be informed that the minimum size of crank shaft approved is 234 mm diameter ( $9\frac{1}{8}$ " )


*M. Cm.*  
9/7/29.



© 2021

Lloyd's Register  
Foundation

MA



CAB