

Received by Chief Ship Surveyor _____

Received from Chief Ship Surveyor _____

14 AUG 1929

VESSEL'S NAME Steel Twin Sc. "ANGLO NO.2" Rpt. B.As. No. 10940**The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.**

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/22).

Nature of Survey _____

The 2nd S.S. No.2 became due 11,28.

The Buenos Aires Surveyors now report the vessel placed in dry dock and the vessel examined with a view to ascertaining the necessary repairs.

The Surveyors recommend that the close ceiling over the deck be removed for the examination of the upper deck plating, 14 shell plates be renewed and 1 doubled.

Four shell plates have now been renewed and one doubled.

Upon receipt by the Owners' local representative of a cable reply from London, instructions were received as per attached letter to abandon the survey.

It is submitted the vessel's class be withdrawn from the Register Book and three dots (...) be inserted in lieu thereof, indicating withdrawal of class at Owners' request.

Withdraw Class.

Insert ...



© 2021

Lloyd's Register
Foundation

00 8804 - 00 8811 - 0226