

8,45.

V

27 Nov 1945

Received by Chief Ship Surveyor.....

Received from Chief Ship Surveyor.....

VESSEL'S NAME "FRESHFORD" REPORT Lth. No. 21504

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The LEITH Surveyors report this Admiralty tender placed in dry dock, bottom coated and minor repairs effected.

Due to damage, cause not stated, temporary repairs effected to indented shell plates (s.s.f) and the Surveyors recommend permanent repairs at the first convenient opportunity.

IT IS SUBMITTED the vessel is eligible to remain as classed with record of docking survey 10.45 subject as recommended.

10.45 Lth. subject.

20.11.45 [Signature]



© 2021

Lloyd's Register Foundation

008812 - 008872 - 0077

Have the Tanks been tested?

Doubling Plates under Sounding Pipes

Salting (State if examined.)

Sails

(med)
verij
✓
lu
7
to
M.
if on
Mont
ls. &c.
ow asc
wed
letter
e of ...
to if n
n bo
ength
r
Warp
d Run