

TELEPHONE: No. 141.

Lloyd's Register of Shipping,

18½, Regent Quay,

Aberdeen, 24th August, 1943.

Reference

S.

Dear Sir,

"Freshener" Aberdeen Report No. 21155.

Subject to Port hawse pipe being renewed, stem bar and indented plating, as reported, being repaired at the first available opportunity.

I am, Dear Sir,
Yours faithfully,

B. Crampton
For The Surveyors.

The Secretary,

WOKINGHAM.



Lloyd's Register
Foundation

008812 - 008822 - 0097

Outside Plating

Steering gear and its connections

Cargo Hatchways

Masts

M

H
R.S.

26 AUG 1943



© 2021

Lloyd's Register
Foundation