

"FRESHENER"

Abn. Rpt. No. 21155.

It is submitted before this case receives the consideration of the Committee, ~~the report be returned to the Surveyors who should be asked to complete it in the usual way and~~ requested to state their recommendations in regard to repairs.



© 2021

Lloyd's Register
Foundation

18.8.43.

008812 - 008822 - 0098

Coamings

Cement or Asphalt

Oil Bunkers

Scuppers

Copper
(S)
When

Boat