

1

Sent to Chief Surveyors \_\_\_\_\_

Received from Chief Surveyors \_\_\_\_\_

VESSEL'S NAME *Stt. Sc. "WILLIAM LUCKENBACH"* Report *Sea* No. *7188*  
*2506*  
*2505*

For the CHIEF SHIP SURVEYOR ~~in connection with the~~

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/82.)

Nature of Survey

*First Entry*

When due

*100 A.1 "with freeboard"**2 Dks & Shelter Dk*

*Cell DB 411 ' 1604t, <sup>Tween Dk Tanks 256t,</sup> / FPT.87t, APT 37t.*

*FK, 8BH, (Cell BH to Shelter Dk 7BH to 2nd Dk), Cen.**Date of build 1913**8.34 Sea**S.S. Sea Ind No 3 - 8.34**note amended class & S.S. notation — leave out A+C P*

deck was in error. A further check was made while vessel was on dry dock and the moulded depths found: Shelter Deck, 39'- 2" Freeboard

008812 - 008822 - 0139



© 2021

Lloyds Register  
Foundation

*5-10-34*  
*all*