





fitted in this Vessel at Seattle.

MARKS ON BOILER NO. 32:.....

No. 32.  
LLOYD'S TEST  
330 Lbs.  
3-22-18 J.H.Y.

No. 32.  
LLOYD'S RETEST  
330 Lbs.  
1-12-33 F.G.A.

MARKS ON BOILER NO. 36:.....

No. 36  
LLOYD'S TEST  
330 Lbs.  
3-27-18 J.H.Y.

No. 36  
LLOYD'S RETEST  
330 Lbs.  
1-12-33 F.G.A.

N.B.—If this Report is copied by copying Press, special care must be taken that the copying paper is not so much damped as to spread the ink, or to cause it to show through to the other side.

THE SURVEYORS ARE REQUESTED NOT TO WRITE ACROSS THE MARGIN.

has a survey also each note on the machinery of the ship.  
If so, the Report sent now, or when will it be sent?



© 2021

Lloyd's Register  
Foundation

10m, 12/22—Transfer Ink.  
(The Surveyors are requested not to write on or below the space for Committee's Minutes.)