

GENERAL REMARKS (State quality of workmanship, opinions as to class, &c.)

MARKS.

No. 32.
LLOYD'S TEST
330 Lbs.
3-22-18 J.H.Y.

No. 32.
LLOYD'S RETEST
330 Lbs.
1-12-33 F.G.A.

No. 36
LLOYD'S TEST
330 Lbs.
3-27-18 J.H.Y.

No. 36.
LLOYD'S RETEST
330 Lbs.
1-12-33 F.G.A.

The two boilers were constructed under Special Survey (See Portland Rpt No.506) and retested by the Surveyors at San Francisco, Dec.1st, 1933. (See S.Fo. Rpt No.7188) same have been installed on board under survey and in accordance with the Rules. All mountings, piping, etc., examined, tested, and fitted as per Rules and in my opinion the two boilers are eligible to be classed in the Register Book.

Certificate (if required) to be sent to
(The Surveyors are requested not to write on or below the space for Committee's Minute.)

The amount of Entry Fee .. £	:	:	When applied for.
Special £	:	✓19.....
Donkey Boiler Fee £	:	:	When received.
Travelling Expenses (if any) £	:	:19.....

Committee's Minute

NEW YORK SEP 20 1934

Assigned See Machy. Rpt form 9
+ NB (fwd) made & fitted 8-34

W.P. Smith
Engineer Surveyor to Lloyd's Register of Shipping



© 2021
Lloyd's Register
Foundation