

W.J. Yarwood & Sons (1938) Ltd., Northwich.

Yard No. 760.

4- DEC 1944

to Chief Surveyors.....

Received from Chief Surveyors.....

SEL'S NAME S.S. "EMPIRE FULHAM" REPORT Liv. No. 121874

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—(Extract from Sub-Committee's Report, 24/5/92.)

re of Survey First Entry When due

This is a sister vessel to the "EMPIRE BARNABY".

\*100A1 "Water Carrier"

1 Dk "Butts of shell & deck plating elec. welded"

Wing tanks in mchy space 20t, DTF 12', 26t, FPT 22t, APT 16t

FK, 5 BH, Cem., Lloyd's A & CP

Q 41' F 14'

Mchy Aft

O.L. 106.3'

b

It is submitted the Surveyors be informed it is concluded the 6"x3"x3" angle stiffeners on the centre line bulkhead are spaced 21" apart as approved and not 31" as reported but they should state if this is so.

© 2020

Lloyd's Register  
Foundation

1.C.8  
28.11.44

6.8.16

Holds. Cargo Tanks

13 1/2 .375 BR

Spacing

008831-008838-0212