

Gunnar Weiburg.

F.E.

Received by Chief Ship Surveyor 8.6.04

Received from Chief Ship Surveyor

VESSEL'S NAME *Sw. S. S. "Uppland"*

Report *Appl.* No. 12370

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

CLASSIFICATION.

Items.	Additions (if any) required by Rules, or as approved.	On account of:—
Main Sheerstrake . .	<i>7/20"</i>	<i>Proportions</i>
Spar Sheerstrake . .		
Description of Framing:— <i>Deep (Bulb angle) framing, as approved.</i> (viz., ordinary, deep, zed, channel or bulb-angle).		

The chain cables are 52 lbs. or 1/10 of one per cent less in weight than required by Table 22.

In other respects This vessel appears to have been built in accordance with the Rules and the approved plans, and it is submitted she is eligible to be classed **† 100 A1 ("Steel")** as recommended.

† 100 A1 ("Steel")

1 DR (In) & deep framing.

M. B = Cell DB a 86' a E 32' f 130' 648t FPT 452 APT 88t

FK 58H Cam. Lloyd's ACP P 27' B 81' F 32'



© 2021 8/6/04

Lloyd's Register Foundation

008855-008862-0233