

C O P Y

# Lloyd's Register of Shipping.

Port SHIMONOSEKI.

23rd June 1941.

Continuation of Shimonosaki  
Damage report dated 30th July 1940.

This is to Certify that

T. Kuniishi.

the undersigned Surveyor to this Society did at the request of

the Owners representative, survey the Steel Single Screw Steamer  
"S. I. A. S. S. O. W. M. A. R. U", 3631 tons gross, of Kobe, on the 29th  
May 1941 and subsequently whilst the vessel lay in dry dock at  
Mikoshima (Shimonosaki) for the purpose of ascertaining the nature  
and extent of damage stated to have been caused by the vessel  
touching lighters at Bungun and found on the 22nd July 1940 whilst  
on a voyage from Bungun to Yawata.

For further particulars see Log Books, and the Shimonosaki  
Damage report, dated 30th July 1940.

Upon further examination by the undersigned, the following  
permanent repairs have now been satisfactorily carried out:-

Shell plates on port side aft.

No. 4 plate in 3rd strake below upper deck sheerstrake has been part  
doubled.

No. 5 plate in 4th strake below upper deck sheerstrake has been  
renewed.

On completion of repairs, the repaired parts were hose  
tested and recoated as necessary.

See also page account.

*T. Kuniishi*  
SURVEYOR TO LLOYD'S REGISTER.

Certificate is issued upon the terms of the Rules and Regulations of the Society, which provide that:—  
the Committees of the Society use their best endeavours to ensure that the functions of the Society are  
performed, it is to be understood that neither the Society nor any Member of any of its Committees is under any  
liability to be held responsible for any inaccuracy in any report or certificate issued by the Society or its  
Committees in any entry in the Register Book or other publication of the Society, or for any error of judgment, default or  
negligence of any of its Committees or any Member thereof, or the Surveyors, or other Officers or Agents of the Society."