

F.E.

Chief Ship Surveyor

Received from Chief Ship Surveyor

NAME *Stl S JO TAYLOR* Rpt. No.

Remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

7
Verse No. *14282*

Depth "d" *23.83*

Fig: Table No. *✓*

Description *Bull angle frames as approved*

Longitudinal No. *35361*

Proportions $\frac{\text{Length}}{\text{Depth}} =$ *10.87*

Sheerstrake *as approved*

Revised Rules

This vessel appears to have been built in accordance with the
and the approved plans, and it is submitted she is eligible to
be classed *✠ 100 A. 1. (Steel)* with freeboard," as
ended. The Summer freeboard of *3 ft - 7 in* from centre of disc
of statutory deck line at — deck, now marked on the
sides, to be inserted in the classification certificate, and
entered in the Register Book, and further, the remaining freeboards,
shown on the accompanying verification form to be inserted in the
certificate of classification.

Stl) + Shelter D^c (Stl)

B. 338' 1202 t, F.P.T. 125 t, A.P.T. 249 t

6 B.H. (Coll B.H. to Shelter D^c, 5 B.H. to 2^d D^c) *Cent. Plydo ACP*

008871-008878-0049

© 2020
Lloyd's Register
Foundation
8
30.9.20