

Port of New York

December 21st 1940

REPORT ON MASTS, SPARS, AND RIGGING.

Having, in accordance with your instructions, examined
Masts, Spars, and Rigging, and Iron Work of same, of the
S Willy at Todds Dry Docks Erie Basin Brooklyn N.Y.

have to report that I found the following rigging and stays in bad
condition and recommend renewal

sixteen(16) shrouds on fore and main mast with turnbuckles, to be
renewed.
all top mast rigging, stays and backstays on fore and main-mast
with turnbuckles, to be renewed.
insulated spring stay between fore and main mast, to be renewed.
fore stay and fore-mast carry-aft preventer stay with turnbuckles
to be renewed.
main-mast preventer carry-aft stay with turnbuckles, to be renewed.
all boom topping lift pennants to be renewed.

William Banks



© 2020

Lloyd's Register
Foundation

008879-008887-0038

15.00.
the Surveyors,
Lloyd's Register of Shipping,