

1

Sent to Chief Surveyors _____

Received from Chief Surveyors _____

VESSEL'S NAME "JOSEPH FLINT". Report _____ Lon. _____ No. 108082a

For the CHIEF SHIP SURVEYOR and CHIEF ENGINEER SURVEYOR.

(In cases which have to be submitted to the Classing Committee "the endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

Nature of Survey _____

When due _____

The Screwshaft Survey became due 9,39.

In reply to enquiry the Owners write that the vessel is employed on Inland waters of the Niger River and comes under the Nigerian Marine for Annual Surveys.

The Society's classification will therefore no longer be retained.

It is submitted the class of the vessel be withdrawn from the Register Book and Three Dots(...) inserted in lieu, ^{withdrawal} indicating of class at Owners' request.

Withdraw class

Insert ...



20.12.39.



Lloyd's Register
Foundation