

AN

D.S. 182

8- APR 1949

Received by Chief Ship Surveyor

Received from Chief Ship Surveyor

VESSEL'S NAME "AVOLA" REPORT Abn. No. 22592

The remarks of the Chief Ship Surveyor are desired on this case for the consideration of the Classing Committee.

("The endorsement to contain a succinct summary of any repairs that have been required and to show the cause or causes of such repairs, and also to bring out clearly any exceptional features in connection with the case, so that the Classing Committee may have all the salient points presented in the endorsement."—Extract from Sub-Committee's Report, 24/5/92.)

The class is subject to shell plates D.4 and 5 (p.s) being renewed at the first opportunity. *See letter 15/4/49.*

The ABERDEEN Surveyors report this trawler placed on pontoon, bottom coated, and minor repairs effected on account of heavy weather.


Nothing was done to the shell plates, as above, which were examined and found to continue efficient.

IT IS SUBMITTED this vessel is eligible to remain as classed, with record of docking 3.49, subject as above.

3.49. Abn, subject.

W.O.I.
2.4.49.

See letter 15/4/49.
The Surveyors should be referred to Circular 1895, and requested to furnish their amended recommendations regarding shell plates D. 4 and D.5 (p.s), which require to be renewed.



Lloyd's Register
Foundation