

COPY

LLOYDS REGISTER ABERDEEN

(16. 1. 46.)

AVOLA DRILLINGS NOTED BUT IN ADDITION TO THOSE PLATES RECOMMENDED
BY YOU FOR RENEWAL ALL PLATES WITHIN MIDSHIP HALF LENGTH WHERE WORN
BELOW POINT THREE THIRTY SHOULD BE RENEWED OR DOUBLED

COMMITTEE

008900-008908-0070