



"AVOLA"

It is submitted the Aberdeen Surveyors,
who have forwarded particulars of the thicknesses
of the shell plating as ascertained by drilling,
be informed that in addition to those ^{plates} suggested by
them for renewal, all plates within the midship
half-length where ~~worn to~~ below .30 should be
renewed or doubled.



15.1.46.



© 2020

Lloyd's Register
Foundation

008900-008908-0072