

REPORT OF SURVEY for REPAIRS, &c.

Date of writing Report 19... When handed in at Local Office 19... Port of London

No. in Survey held at... Date, First Survey... Last Survey 19...
Reg. Book. "Nancy Hague" (No. of Visits)

11898 on the Wood, Iron or Steel Built at Middlesbrough By whom Smith's Dock Co. Ltd. When 1911 6

TONNAGE:- GROSS 299 Owners Mrs Docters Wm. Franklin & Co. (Fleetwood) Ltd. Owners' Address (if not already recorded in Appendix to Register Book).
UNDER DK. 258 Managers Port belonging to Fleetwood

Surveyed Afloat or in Dry Dock? Name of Dock Destined Voyage

B=CellDBorDBa feet; uE&B feet; f feet
Total capacity tons. FPT tons; APT tons; MT feet tons.

N.B.—All alterations in the existing records should be underlined.
If the Vessel has Water Ballast Tanks, state whether the manhole covers have been removed, and the insides of the tanks examined. Also state the amount of deterioration (if any) found in the thicknesses of the floors, framing, and of the inner bottom plating, especially in the boiler space.

Last Report, No. 107881. Port Liverpool

Periodical Surveys, when held, must be reported in detail and seriatim in the terms of the Rules. State clearly the cause of Repairs, if any, and, in detail, the nature and extent of Examinations and subsequent repairs. Repairs on account of Damage (the cause of which must be stated) should be separated from Repairs due to other causes; and besides being detailed in the body of the report, should be summarised in the form shown below. Whenever the replacement of Anchors or Chains is reported the particulars should be clearly stated in the space provided on the back of this form. State also the dates and initials of any letters respecting this case.

damage cases where the Surveyor has not made a special damage report he is required to state whether he offered his services for this purpose and to whom and why they were declined

Particulars of Classification (which must be inserted precisely as in Register Book & Supplements)

CHARACTER, &c. for Special Survey, Date of last survey and of Periodical Surveys.	Year allowed how long expired.	Machinery and Beller Surveys (including date of N.B., if any).
+100A1 The Trawler 10.36.		+LMC MS 10.32. BS 5.36 Cl. N. 2.35
1911. No 3-10, 24		
1911 No 2-33		

Society's Freeboard (if assigned) as painted on Ship and now verified } fl... ins.

Was a damage report made by anyone else? If so, by whom?

REPAIRS, OR EXAMINATION AS PER RULE, FOR

SUMMARY OF DAMAGE REPAIRS:—	Shell Plates.	Frames.	R. Frames.	Floors and Bracket Floors	Beams.	Inner Bottom Plates.	Dk. Plates.	Other Items:—
Renewed								
Removed and Faired or Repaired								
Faired or Repaired in place								

PRESENT CONDITION OF THE

Decks	State if Tanks have been examined inside	Air and Sounding Pipes	Copper, or Y.M. of Wood Vessels (State if on Felt). When put on, Month Year.
Caulking of Decks	State if Tanks now tested	Dblng. Plates under Sounding Pipes	Boats
Coamings	Bulkheads	Engine Room Skylights	Masts, Yards, &c.
Beams & Fastenings	Ceiling	Coal Bunkers, Open'gs, Lids, &c.	Condition, how ascertained (state if wedges removed)
Outside Plating	Cement or Asphalt (State which.)	Oil Bunkers	Sails
" " in way of sidelights	Rudder	Scuppers	Equipment letter
Breasthooks	Steering gear and its connections	Cargo Hatchways	Anchors, No. of
Transoms	Windlass	Hatches	Chain Locker
Frames	Have pumps now been examined and found efficient?	Planking of Wood Vessels	Cables (state if now ranged)
Reverse Frames	Have Sluice Valves now been examined and found efficient?	Caulking ditto	" length mean diam. (on board)
Longitudinals	Have Watertight Doors now been examined and found efficient?	Treenails ditto	" Rule length size
Transverses	Have Ventilators and their Coamings been examined and found efficient?	Breasthooks & Stemson ditto	Hawser & Warps
Floors		Transoms Pointers, & Crutches ditto	Standing and Running Rigging
Keelsons		Timbers of Frame at openings ditto	
Stringers		Ditto Ditto at other places ditto	
Inner Bottom Plating		Stringers, Clamps & Sheifs ditto	
		Salting (State if examined.)	

General Observations, Opinion as to Class, Recommendation, &c.:

State clearly whether any and, if so, what alteration is suggested to be made in the existing classification and notification of the vessel in the Register Book consequent upon this survey, thus, for example:—"to remain as now classed in the Register Book without fresh record of Survey," "to remain as classed and to have record of survey, 1,24," or "to remain as classed and to have record of survey, 1,24, and the notations of ss. No. 1-24 and pND24, &c."

Survey Fee (per Section 20)	£	Fees applied for,	19
Special Damage or Repair Fee (if any) (per Sec. 20)	£	Received by me,	19
Travelling Expenses (if chargeable)	£		
Second Surveyor's Fee (if any)	£		

Committee's Minute
Character Assigned
TUE 14 DEC 1937
Exchanged class with Red Line
Surveyor to Lloyd's Register of Shipping.
Special General Committee
Thursday 16th December 1937
Decision of Classing Committee confirmed

10m. 12.35. Transfer Ink. (The Surveyors are requested not to write on or below this space for Committee's Minute.)

Is Certificate required? If so, to be sent to