



# Lloyd's Register of Shipping,

819/48.

Gdynia, December 9th 1948

Dear Sir,

S.S. "KILINSKI" Report No.2108.

Further to my letter of the 12th ultimo in respect of the above vessel, Mr. Hauser writes ' It is confirmed that tanks for carrying oil fuel need not be examined internally. The fire extinguishing apparatus actually referred to a CO<sub>2</sub> system fitted in the machinery space near the after end of the boilers and it appeared to be fitted as a general fire extinguishing system for the whole machinery space - portable fire extinguishers were fitted and the CO<sub>2</sub> and foamite extinguishers were found to be in order. The economisers were examined at the recent Boiler Survey.'

It is regretted that these points have arisen and it would be appreciated if the Reports 8 and 9 could be amended.

Yours faithfully,

*H. Seenehard*

The Secretary,  
London



© 2020

Lloyd's Register  
Foundation

M+E

Referred to Mr. Perris.

J.C.D.

Notes + in order.  
sent 16/12/48



© 2020

Lloyd's Register  
Foundation